

# State of Utah

# Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Dennis Oakley Environmental Engineer
Company	Kenneth S. Fleck Manager of Geology and Environ
OGM	Steve Demczak Environmental Scientist III

# **Inspection Report**

Permit Number:	C0150017		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, April 15, 2008		
Start Date/Time:	4/15/2008 10:00:00 AM		
End Date/Time:	4/15/2008 2:00:00 PM		
Last Inspection:	Tuesday, March 18, 2008		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's, Windy InspectionID Report Number: 1611

Accepted by: jhelfric

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DES BEE DOVE MINE** 

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY** 

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

#### **Current Acreages**

154.86	<b>Total Permitted</b>
36.22	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

#### **Mineral Ownership**

**Types of Operations** ✓ Federal ✓ Underground State Surface County ☐ Loadout Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Wednesday, April 16, 2008

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 15, 2008

Page 2 of 3

# REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	$\checkmark$		$\checkmark$	
2.	Signs and Markers	<b>V</b>			
3.	Topsoil	<b>✓</b>		<b>V</b>	
4.a	Hydrologic Balance: Diversions	<b>V</b>		<b>V</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>✓</b>		<b>✓</b>	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		<b>✓</b>		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	<b>V</b>		<b>✓</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	<b>V</b>		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	<b>✓</b>		<b>✓</b>	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations	<b>✓</b>		<b>✓</b>	
16.a	Roads: Construction, Maintenance, Surfacing		<b>✓</b>		
16.b	Roads: Drainage Controls		<b>✓</b>		
17.	Other Transportation Facilities	✓		✓	
18.	Support Facilities, Utility Installations	<b>✓</b>		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 15, 2008

Page 3 of 3

# 1. Permits, Change, Transfer, Renewal, Sale

No permitting action has been submitted to the Division since the last inspection.

### 3. Topsoil

All topsoil has been used in reclamation of the site.

# 4.a Hydrologic Balance: Diversions

The diversions were inspected and are consturcted as designed.

# 4.b Hydrologic Balance: Sediment Ponds and Impoundments

No impoundments are located on site.

# 4.c Hydrologic Balance: Other Sediment Control Measures

No sediment was noticed leaving the mine site. The permittee has pocks the site holding the water in the depressions.

#### 8. Noncoal Waste

The area is clear of non coal waste materials.

# 10. Slides and Other Damage

No slides were noticed during the inspection.

### 12. Backfilling And Grading

The mine site is totally backfilled and graded.

# 15. Cessation of Operations

The mine site is reclaimed.

### 17. Other Transportation Facilities

The cattle trail was inspected and could use some maintenance by removing rocks and grading.

### 18. Support Facilities, Utility Installations

No support facilities are on the site.